



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re patent of:

Yo TSURUMI et al.



ATTN: CERTIFICATE OF
CORRECTIONS BRANCH

Patent No. 7,070,533

Issued: July 4, 2006

Attorney Docket No. 59558.00025

For: INTERNAL TEETH OSCILLATION TYPE INNER GEARING PLANETARY
GEAR SYSTEM

PETITION TO ACCEPT REQUEST FOR
CERTIFICATE OF CORRECTION UNDER 37 CFR 1.183

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

July 20, 2006

07/21/2006 SDENBOB1 00000042 502222 7070533

02 FC:1462 270.00 DA 130.00 OP


Sir:

Petition is herewith made, under 37 C.F.R. 1.183, to waive the requirements of 37 C.F.R. 3.81 and to accept the filing of the attached Request for Certificate of Correction under 37 CFR 1.323 and issue a certificate of correction for the above identified patent.

The Certificate of Correction is necessary to correct the assignee's name to be **SUMITOMO HEAVY INDUSTRIES, LTD.**. At the time of paying the Issue Fee, the assignee was incorrectly identified as being "SUMITO HEAVY INDUSTRIES, LTD." through error without deceptive intent. This correction is supported by the Assignment. It is requested that the requirements of 37 C.F.R. 3.81 be waived, the filing of the attached Request for Certificate of Correction under 37 CFR 1.323 be accepted and that a certificate of correction for the above identified patent be issued to correct this error.

A check in the amount of Two Hundred and Thirty Dollars (\$230.00), One Hundred Thirty dollars (\$130.00), of which, is for the necessary fee under 37 C.F.R. 1.17(h)(1) to cover the cost of this petition, and is attached herewith. Any additional fees which may be due with respect to this paper may be charged to Counsel's Deposit Account No. 50-2222.

Respectfully submitted,



Arlene P. Neal
Registration No. 43,828

Customer Number 32294
SQUIRE, SANDERS & DEMPSEY LLP
14TH Floor
8000 Towers Crescent Drive
Tysons Corner, Virginia 22182-2700
Telephone: 703-720-7800
Fax: 703-720-7802

APN:kmp

Enclosures: Request for Certificate of Correction
Form PTO-1050
Check No. 14751